



Miller

Millermatic
252

Castle
MIG Welder

Miller
252



Miller
Millermatic 250X

V
V
VOLTAGE

POWER
ON
OFF

BE



CAUTION

9159


Miller

Millermatic 251


Miller

CAUTION


NOT TO BE USED



Shopmaster 300AC/DC
WELDING POWER SOURCE



OUTPUT (CONTACTOR)
ON
REMOTE 14



PANEL
REMOTE 14

SERIAL NO. K020448
STOCK NO. M0148
VOLTS 200/240/480
AMPERES 100/150/240
KW 11.7
PHASE 1
HERTZ 60



MADE OUTPUT
VOLTS
DC 200
AC 240
DUTY CYCLE
MAX. 100%
MAX. 100%

OUTPUT SELECTOR
STAN/D BY



WARNING: ELECTRIC SHOCK
CAN KILL.
DO NOT USE AC OUTPUT IN DANGEROUS AREAS IF MOVEMENT IS COMBINED OR IF THERE IS A DANGER OF FALLING.
USE AC OUTPUT ONLY IF REQUIRED FOR THE WELDING PROCESS.
IF AC OUTPUT IS REQUIRED, USE REMOTE OUTPUT CONTROL.

BE SURE INDICATOR POINTS DIRECTLY AT DESIRED OUTPUT.
DO NOT SWITCH UNDER LOAD

VOLTMETER
OPTIONAL

AMMETER
OPTIONAL



Shopmaster
CV/CC - AC/DC
WELDING POWER SOURCE
MILLER ELECTRIC MFG. CO. APPLETON, WI, USA

WARNING
Do Not Remove, Destroy, Or Cover This Label

ELECTRIC SHOCK CAN KILL
• Always wear dry insulating gloves.
• Insulate yourself from work and ground.
• Do not touch the power source when it is energized.
• Disconnect input power before working on it.
• Keep all parts and covers securely in place.

FUMES AND GASES CAN BE HAZARDOUS
• Keep your head out of the fumes.
• Ventilate area or use breathing device.
• Read Material Safety Data Sheets (MSDS) and manufacturer's instructions for details.

ARC WELDING CAN BE HAZARDOUS
• Heat and intense light rays can cause eye and skin damage.
• Only qualified persons can do welding, brazing, or cutting.
• Wear eye protection and clothing that will protect you from sparks and molten metal.
• Do not wear flammable clothing.
• Do not wear jewelry.

ARC RAYS CAN BURN YOUR EYES AND SKIN
• Shield your eyes and skin from the arc.
• Use proper welding technique to minimize spatter.
• Wear proper eye and skin protection.

UNCHOC ELECTRIQUE PEUT ETRE FATALE
• Toujours porter des gants isolants secs.
• Toujours vous isoler du travail et de la terre.
• Ne pas toucher la source d'alimentation quand elle est sous tension.
• Débrancher l'alimentation avant de travailler sur elle.
• Garder toutes les pièces et couvercles fermement en place.

LES FUMES ET LES GAZ PEUVENT ETRE DANGEREUX
• Gardez votre tête hors des fumées.
• Ventilez l'aire ou utilisez un appareil respiratoire.
• Lisez les Feuilles de Données de Sécurité (FDS) et les instructions du fabricant pour plus de détails.

LE SOUDAGE A L'ARC PEUT ETRE DANGEREUX
• La chaleur et les rayons lumineux intenses peuvent causer des brûlures et des lésions à la peau.
• Seul le personnel qualifié peut effectuer le soudage, le brasage ou le découpage.
• Portez une protection adéquate pour vos yeux et votre corps.
• Ne portez pas de vêtements inflammables.
• Ne portez pas de bijoux.

LES RAYONS A L'ARC PEUVENT BRULER VOS YEUX ET VOTRE PEAU
• Protégez vos yeux et votre peau de l'arc.
• Utilisez la bonne technique de soudage pour minimiser les éclats.
• Portez une protection adéquate pour vos yeux et votre peau.